


MP3 report - week 17 26/04/2010 - 02/05/2010 17 interventions

MP3/QPS team in CCC

Interventions evolution


Technical stop so no intervention for 2.5 days then increased Recovery of technical stop






RQTF/D & feedback (continued) [1/2]


- During technical stop, the time discrimination was increased from 20ms to 200ms
- Test performed in 56 on Wed 28/04 and successful



RQTF/D & feedback (continued) [2/2]

Trips but system reacted as expected






28/04: Trip of RQTD.A45B1 during test due to wrong polarity (solved in tunnel by MPE piquet) but the 190 ms delay is well seen

Monday Morning Mee

RCBH19.L3B2 & RCBV19.L3B1


Was locked due to problem on a cryo valves for the beam screen circuit cooling. Valve was changed during technical stop by CRG and test performed to validate it (29/04 profiting from an access in 45)





QPS_OK check is now active for all 600 A circuits with a check every 10 minutes. If verified during short glitch, injection is not possible for 10 minutes or interlock has to be masked

- Circuits masked after verification that QPS was OK:
 - + RQS.R5B1, RCS.A12B1, RCO.A81B1
 - + QPS board reset does not solve the issue



Monday Morning Meeting: 310 01 May 2010

RB.A34, RQF/D.A34: Loss of com + QPS_OK

On 1st of May @ 7:03 loss of QPS_OK for mains in 34 for ¼ of the sector + Joint BE-CO/MPE/MP3 effort allowed localising the problem to a badly inserted/clamped wire inside the WorldFip connector of the nQPS crate B23R3, resulting in the loss of communication for the whole segment + In the meantime, as magnets were at injection current, interlock was masked but ramping-up and pre-cycle were forbidden



Other issues since April 26th

28/04 : Power cut (EDF 400 kV) caused trip of 11 circuits (P1,2,8)

Heaters discharged and checked

- ROTD.A56B1 (twice) : Solved by PC piquet
- Undulator RU.L4 reset during precycle
 Both presently OK but RU.L4 slowly drifting



100428-061006.201_RQ10.L8 100428-061006.179_RQ10.R2 100428-061006.176_RQ10.R8 100428-061006.158_RQ10.L2 100428-061006.156_RQ6.L1 100428-061006.146_RQ5.L1 100428-061006.146_RD2.R1 100428-061006.144_RQ8.R1 100428-061006.144_RQ8.L1 100428-061006.144_RQ8.L1

- RB.A78: Trip on 29/04
 Filter card exchanged by EPC+ switch in RR77 (Param modified, now OK)
- RCD.A78B1 : One board with com pb solved from CCC (Slow Power cycle)
- RSS.A45B1 : Trip at 0 current (PC)
- RQTD.A45B1: Trip due to HW limit @ 120A and induced trip of RSD2.A45B1
- RQTD.A81B2: Tripped 3 times due to external water fault (30/04)
- RQF.A23 : Loss of QPS_OK ; reset (02/05)