




# BL due to VAC



XXX





# Beam current and maximum losses





# Beam current and maximum losses





# Injection losses





# Cleaning after injection





# Zoom in IP7





# Loss maps in May 2010



# Steady losses



# Cleaning in these conditions



# Zoom in IP7

